



Operation of Long-Pulse Magnet No. 9 (two-stage coil) has been suspended after abnormalities were detected in its magnetic field waveform.

We will continue with Magnet No. 8 (single coil).

Photo: Long-Pulse Magnet No. 9, pulled out because of suspected damage.